

Xhorse Dolphin XP-005 Key Cutting Machine Update Info:

Xhorse Dolphin XP-005 V1.4.0 (2020-03-28)

- * This version need to update firmware
 - * Improve some cutting strategy
 - * Change standard double sided default tip cutting strategy
 - * Fix Electrical Conductivity Measurement bug
 - * Fixed cutting problem of 2 Track external
 - * Fix some universal key duplication bugs
- Please Use Xhorse Update Kit to update.

Xhorse Dolphin XP-005 V1.3.8 (2020-01-13)

This version need to update fireware
Add "Cut by single-bitting" function (Not support internal track key blank)
Add "Parameter micro-adjust" function
Improve high level adjustment function, not need do clamp calibration every time after high level adjustment
Fix cutting depth not accurate problem
Fix HU66 EXT 9th slot width problem
Fix some universal key duplication bugs

Xhorse Dolphin V1.2.7 (2019-11-01)

This version need to update firmware
Fix some bugs
Optimization the slope of track internal
Optimization the slope and flat of VA2T
Modified the tail file of HON66 and HU66
Fixed the top abrasion invalid problem
Fixed the M1 clamp key cutting error
Fixed secondary processing cutting problem
Fixed the cut problem of the customize key data
Fixed firmware upgrade instability problem
Fixed the cutting problem of FO21
Fixed cutting problem of 4 Track external
Add bluetooth error remind function

Xhorse Dolphin V1.2.3 (2019-09-09)

This version need to update firmware
Fix some bugs
Fix VA2T cutting strategy

Xhorse Dolphin V1.1.9 (2019-06-24)

This version need to update firmware
Fix HU66EXT cutting problem

Xhorse Dolphin V1.1.8 (2019-06-13)

This version need to update firmware
Fix Channel track type header cutting error problem
Fix some 4 Track internal type can not cutting problem