

## **Xhorse VVDI2 Software Update to V6.7.5**

2020-05-28

Requires firmware upgrade to V6.7.5

### VAG V6.7.5

1. Improvement for autodetect VAG immobilizer system
2. Improvement for update FRF, SGO file
3. Bugfix

### BMW V6.7.5

1. Improvement for CAS3 key learning
2. Bugfix

### Transponder Programmer V6.7.5

1. Improvement for make proximity remote
2. Immobilizer data tool:Asia->Hyundai->Santa Fe->2008-MPC5XX bugfix
3. Improvement for clone ID70/ID83
4. Special chip: Add new ID47 for GreatWall ORA
5. Bugfix

### Copy 48 (96 bits) V6.7.5

1. Bugfix

### J2534 V6.7.5

1. Bugfix

### Online Update Tool V6.7.5

1. Bugfix

### Quick Start V6.7.5

1. Bugfix

## VVDI2 latest software version V6.7.2 update

Date: 2020-04-14

Require firmware V6.7.2

===== VAG V6.7.2 =====

1. Improvement for autodetect VAG immobilizer system
2. Bugfix

===== BMW V6.7.2 =====

1. Improvement for CAS4 OBD: Support OBD fix remote and smart not working
2. Bugfix

### VVDI2 latest software version V6.7.0 update

Data: 2020-03-31

Require firmware V6.6.8

===== VAG V6.7.0 =====

1. Improvement for autodetect VAG immobilizer system
2. Bugfix

===== BMW V6.7.0 =====

1. Add unlock CAS4 fast mode(5M48H/1N35H/1L15Y):
  - 1). Unlock CAS4 only require 2 minutes
  - 2). Support backup D-FLASH(EEPROM), P-FLASH via OBDII
  - 3). Support exchange CAS4 via OBDII
2. Improvement for CAS4 OBD prepare dealer key
3. Bugfix

===== Porsche V6.7.0 =====

2. Bugfix

===== PSA V6.7.0 =====

2. Bugfix

===== Transponder Programmer V6.7.0 =====

1. Add Toyota 8A all key lost(Non-smartkey): Menu->Toyota 8A immobilizer system, Require 8A all key lost adapter.
2. Immobilizer data tool: Asia->Suzuki->Swift->1996 93C66 bugfix
3. Immobilizer data tool: Asia->Toyota->Camry->ECU -2004 93C56(
  - 2) bugfix
4. Immobilizer data tool: Asia->Toyota->Avalon->ECU-93C56 bugfix
5. Bugfix for copy ID67 transponder
6. Bugfix

===== Copy 48 (96 bits) V6.7.0 =====

1. Bugfix

===== J2534 V6.7.0 =====

1. Bugfix

===== Online Update Tool V6.7.0 =====

1. Bugfix

===== Quick Start V6.7.0 =====

1. Bugfix

### VVDI2 latest software version V6.6.9 update

Data: 2020-01-13

Require firmware V6.6.8

===== VAG V6.6.9 =====

1. Improvement for autodetect VAG immobilizer system
2. Add synchronize function: Menu->Synchronize device time
3. Bugfix

===== BMW V6.6.9 =====

1. Improvement for CAS4 OBD prepare dealer key
2. Improvement for FEM/BDC prepare dealer key
3. Add synchronize function: Menu->Synchronize device time
4. Add reset ELV function for BDC(Only for cars with ELV)
5. Bugfix

===== Porsche V6.6.9 =====

1. Add synchronize function: Menu->Synchronize device time
2. Bugfix

===== PSA V6.6.9 =====

1. Add synchronize function: Menu->Synchronize device time
2. Bugfix

===== Transponder Programmer V6.6.9 =====

1. Add synchronize function: Menu->Synchronize device time
2. Immobilizer data tool: Asia->Mitsubishi->ASX->2011 24C16 support VVDI proximity remote, you can have proximity function without key learning
3. Immobilizer data tool: USA->Buick->Century->2000 68HC08 bugfix
4. Immobilizer data tool: Euro->Volvo->XC90 2004- 93C86
5. Bugfix

===== Copy 48 (96 bits) V6.6.9 =====

1. Add synchronize function: Menu->Synchronize device time
2. Bugfix

===== J2534 V6.6.9 =====

1. Bugfix

===== Online Update Tool V6.6.9 =====

1. Bugfix

===== Quick Start V6.6.9 =====

1. Bugfix

## VVDI2 Latest Software V6.6.7 Released Note:

2019-11-21

\*\*\* Require firmware V6.6.5

\*\*\*\*\*

\*\*\*

===== VAG V6.6.7 =====

1. Add German language
2. Improvement for autodetect VAG immobilizer system
3. Bugfix

===== BMW V6.6.7 =====

1. Improvement German language
2. Improvement for CAS4/CAS4+ key learning
3. Add CAS4-1L15Y type prepare dealer key via OBDII
4. Bugfix

===== Porsche V6.6.7 =====

1. Add German language
2. Bugfix

===== PSA V6.6.7 =====

1. Add German language
2. Bugfix

===== Transponder Programmer V6.6.7 =====

1. Add German language
2. Immobilizer data tool: Asia->China immobox->Delphi immobox support new type
3. Immobilizer data tool: Europe->Rover->Discovery->Discovery3 support prepare dealer key with VVDI super chip
4. Immobilizer data tool: Europe->VW->VDO dashboard bugfix for PIN display
5. Immobilizer data tool: Asia->Datong->V80 bugfix for PIN display

## 6. Bugfix

===== Copy 48 (96 bits) V6.6.7 =====

1. Add German language
2. Bugfix

===== J2534 V6.6.7 =====

1. Add German language
2. Bugfix

===== Online Update Tool V6.6.7 =====

1. Add German language
2. Bugfix

### **VVDI2 Latest Software V6.6.6 Released Note:**

Release Date 2019-09-19 Requires firmware V6.6.5

VAG V6.6.6

1. Bugfix for read touareg ECU PIN code(ME7)
2. Improvement for autodetect VAG immobilizer system
3. Bugfix

BMW V6.6.6

1. Improvement for CAS4/CAS4+ key learning
2. Bugfix

Transponder Programmer V6.6.6

1. Special transponder: Bugfix for Buick excelle XT 4D 80Bit
2. Special transponder: Bugfix for Buick excelle 4D 80Bit
3. Immobilizer data tool: Asia->Nissan->Cima 93C46 4D
4. Bugfix

Update Online via Upgrade Kit App

### **VVDI2 Latest Software V6.6.5 Released Note:**

\* 2019-08-29

\*\*\* Require firmware V6.6.5

===== VAG V6.6.5 =====

1. Improvement for autodetect VAG immobilizer system
2. Bugfix

===== BMW V6.6.5 =====

1. Improvement for CAS4/CAS4+ via OBDII
  - 1). Support unlock CAS4 directly, no need update CAS4 flash
  - 2). Improvement for key learning
2. Bugfix

===== Porsche V6.6.5 =====

1. Bugfix

===== PSA V6.6.5 =====

1. Bugfix

===== Transponder Programmer V6.6.5 =====

1. Bugfix for generate and copy Toyota H chip with VVDI su per chip
2. Immobilizer data tool: Asia->Nissan->Note 2004 95080 bugfix
3. Bugfix

===== Copy 48 (96 bits) V6.6.5 =====

1. Bugfix

===== J2534 V6.6.5 =====

1. Bugfix

===== Online Upate Tool V6.6.5 =====

1. Bugfix

===== Quick Start V6.6.5 =====

1. Bugfix

#### **VVDI2 Latest Software V6.6.1 Released Note:**

\* 2019-08-20

\*\*\* Require firmware V6.6.1

===== VAG V6.6.1 =====

1. Improvement for autodetect VAG immobilizer system
2. Bugfix

===== BMW V6.6.1 =====

1. Support CAS4/CAS4+(XEP100 series, 5M48H/1N35H) type with OBDII
  - 1). Support all CAS4/CAS4+ encrypt version with 5M48H/1N35H chip
  - 2). Support prepare dealer key with OBD (We suggest use ignition switch prepare key)

- 3). Support reset mileage in CAS4 module
2. Bugfix

===== Porsche V6.6.1 =====

1. Bugfix

===== PSA V6.6.1 =====

1. Bugfix

===== Transponder Programmer V6.6.1 =====

1. Immobilizer data tool: Support copy start, no need write EEPROM back
  - 1). Support 98% types: 11, 12, 13, PCF7935, PCF7936, 48, 4C, 4D, 4E, 4D DST+, 8C, 8E etc.
  - 2). Require use VVDI super chip and select an used key position
  - 3). The new key can start car directly without write back EEPROM
2. Improvement for copy 46 and copy 4D
3. Immobilizer data tool: Asia->Mazda->MPV 24C02 2005 - 8C
4. Immobilizer data tool: Asia->Mitsubishi->Grandis - 24C02 show PIN CODE
5. Immobilizer data tool: Asia->Ssangyong->>Action Diesel 9S12 - 2011
6. Immobilizer data tool: Asia->KIA->Sportage 2008 - MPCxx
7. Immobilizer data tool: Asia->Hyundai->I30 2012 - STM
8. Immobilizer data tool: Asia->Brilliance->M2 - 93C66
9. Immobilizer data tool: Europe->VW->Santana 93C56 bugfix
10. Immobilizer data tool: Europe->Peugeot->Peugeot 607 2001
11. Immobilizer data tool: Europe->Opel->Mokka 2008 - 24C16
12. Immobilizer data tool: Europe->Volvo->S60 2010 - NEC
13. Immobilizer data tool: Europe->Renault->Master 2013 - NEC
14. Immobilizer data tool: Europe->VW->Passat VDO 1997 - 93C66
15. Immobilizer data tool: American->Ford->Transit 2017 - NEC
16. Bugfix

===== Copy 48 (96 bits) V6.6.1 =====

1. Bugfix

===== J2534 V6.6.1 =====

1. Bugfix

===== Online Update Tool V6.6.1 =====

1. Bugfix

===== Quick Start V6.6.1 =====

1. Bugfix

**VVDI2 Latest Software V6.6.0 Released Note:**

Date:18-07-2019

VAG V6.6.0

1. Improvement for autodetect VAG immobilizer system
2. Bugfix

BMW V6.6.0

1. Improvement for FEM/BDC key learning
2. ECU/CAS ISN: Improvement decode B38/B48 ISN with EEPROM dump
3. Bugfix

Porsche V6.6.0

1. Bugfix

VVDI2 PSA V6.6.0

1. Bugfix

Transponder Programmer V6.6.0

1. Fixbug for make chevrolet epica with VVDI super remote
2. Support copy remote with VVDI super remote
3. Generate Toyota H chip with VVDI super chip no need boint points
4. Special transponder: Add some special transponders(ID70 Kaiyue, ID70 Excelle, ID82G Sabru, ID47 Honda A/G, ID49 USA Ford)
5. Immobilizer data tool: Aisa->Mazda->8C chip bugfix
6. Immobilizer data tool: Europe->Iveco 95640
7. Immobilizer data tool: Europe->Rover 95320 bugfix
8. Immobilizer data tool: Asia->Nissan Micra 93C56 - 2005
9. Immobilizer data tool: Asia->Ssangyong Action 9S12 - 2011
10. Immobilizer data tool: Asia->SAIC Datong V80 95160
11. Immobilizer data tool: Asia->SAIC kaiyue 9S12 - 2013-
12. Immobilizer data tool: America->Ford Cargo 24C64 - 2014-
13. Immobilizer data tool: America->Buick Excelle 9S12 - 2013-
14. Immobilizer data tool: Europe->Fiat Palio 95160 - 2012-
15. Immobilizer data tool: Europe->MAN truck M29W160
16. Bugfix

Copy 48 (96 bits) V6.6.0

1. Bugfix

J2534 V6.6.0

1. Bugfix

Online Update Tool V6.6.0

1. Bugfix

Quick Start V6.6.0

1. Bugfix

**VVDI2 Latest Software V6.5.0 Released Note:**

**Date:23-04-2019**

**VVDI2 VAG V6.5.0:**

1. Improvement for Audi A6/Q7(IMM4) adapt Gearbox
2. Bugfix for MQB35xx write immo data
3. Improvement for autodetect VAG immobilizer system
4. Bugfix

**VVDI2 BMW V6.5.0:**

1. Improvement for FEM/BDC key learning
2. ECU/CAS ISN: Support load and decode B38/B48 ISN with EEPROM dump
3. KM repair: Support ALL eeprom read by VVDIProg M35080, 35160, 35128
4. Bugfix

**VVDI 2 Porsche V6.5.0:**

1. Bugfix

**VVDI 2 PSA V6.5.0:**

1. Bugfix

**VVDI2 Transponder Programmer V6.5.0:**

1. Support VVDI super chip, you can change to any type in the list:  
11, 12, 13, PCF7935, PCF7936, PCF7937, PCF7938, PCF7939, PCF7946, 48, 4C, 4D, 4D(80), 4E, 8A, 8C, 8E
2. Special transponder: Support use VVDI super transponder, it can use reusable, never lock
3. Copy transponder: Support clone 4D transponder
4. Copy transponder: Support clone 4E transponder
5. Copy transponder: Support clone Ford ID83, Kiv ID70
6. Copy transponder: Support clone Toyota H transponder – Require use VVDI super chip
7. Copy transponder: Support clone 8C/4C transponder – Require use VVDI super chip

8. Immobilizer data tool: Euro->Renault->Duster->2010- 95040
9. Immobilizer data tool: Euro->Chevrolet->Silverado->2011 9S08
10. Immobilizer data tool: Asia->Toyota->Corolla->2004 93C66 (ID4C)
11. Immobilizer data tool: Asia->SAIC->Roewe 360 95160
12. Bugfix for electronic monitor key
13. Bugfix

**VVDI2 Copy 48 (96 bits) V6.5.0:**

1. Bugfix

**VVDI2 J2534 V6.5.0:**

1. Bugfix

**VVDI 2 Online Update Tool V6.5.0:**

1. Bugfix

**VVDI2 Quick Start V6.5.0:**

1. Bugfix

Top

Post Reply Quick-mod tools 1 post • Page 1 of 1

Return to “Software & Updates”

**VVDI2 Software Version V6.1.0 update**

\*\*\*\*\*

\*\*\*\*\*

\*\*\* 2018-01-07

\*\*\* Require firmware V6.1.0

\*\*\*\*\*

\*\*\*\*\*

===== VAG V6.1.0 =====

1. Improvement for MQB prepare dealer key
  - a). Support change MQB key ID(support GEKO online), require use VVDI proximity remote
  - b). Support save synchronize data when make key with working key
  - c). Support make dealer key with immo data and synchronize data while all key lost
2. VW MQB add new type: Dashboard version 0555, 0556
3. Improvement for autodetect VAG immobilizer system
4. Support some NEC24C32 TFT dashboard
5. Bugfix

===== BMW V6.1.0 =====

1. ECU /CAS ISN: Bugfix for change ISN for F series

2. FEM/BDC make key: Add new version, support car until 2018.11
3. FEM/BDC backup coding: Add new version, support car until 2018.11
4. Bugfix for MSV70 read ECU synchronize code(2 Bytes)
5. Bugfix

===== Porsche V6.1.0 =====

1. Bugfix

===== PSA V6.1.0 =====

1. Bugfix

===== Transponder Programmer V6.1.0 =====

1. Support generate MQB proximity remote: require use vvdI proximity remote and download latest remote database
2. Improvement for vvdI special transponder
3. Immobilizer data tool: Euro->BMW->motorcycle add new type
4. Immobilizer data tool: Euro->Iveco->Daily 93C56 bugfix
5. Immobilizer data tool: Asia->Isuzu->SX4 TC1762 bugfix
6. Immobilizer data tool: Asia->SAIC->Roewe750 add new type
7. Bugfix

===== Copy 48 (96 bits) V6.1.0 =====

1. Bugfix

===== J2534 V6.1.0 =====

1. Bugfix

===== Online Update Tool V6.1.0 =====

1. Bugfix